

**ROCKY FLATS PLANT
EMD OPERATING
PROCEDURES MANUAL**

Manual No.: 5-21000-OPS-AP
Procedure No.: Table of Contents, Rev 1
Page: 1 of 2
Effective Date: 11/11/91
Organization: Environmental Management

THIS IS ONE VOLUME OF A SIX VOLUME SET WHICH INCLUDES:

**VOLUME I: FIELD OPERATIONS (FO)
VOLUME II: GROUNDWATER (GW)
VOLUME III: GEOTECHNICAL (GT)
VOLUME IV: SURFACE WATER (SW)
VOLUME V: ECOLOGY (EE)
VOLUME VI: AIR (AP)**

**TABLE OF CONTENTS
FOR VOLUME VI: AIR**

Proc. No.	Title	Rev. No.	Effective Date
AP.01	Effluent Tritium Sample Collection	0	10/04/91
DCN 91.01	Seal inspection requirement	0	11/08/91
AP.02	Tritium Sampler Calibration	0	10/04/91
DCN 91.01	Seal inspection requirement	0	11/08/91
AP.03	Effluent Air Radioparticulate		
AP.04	Effluent Air Radioparticulate Sample Calibration		
AP.06	Effluent Air Pitot Tube Inspection and Replacement		
AP.08	Volumetric TSP/PM ₁₀ Calibration , Ambient Air Particulate Sampling High Volume Method	0	10/01/91
AP.09	Ambient TSP/PM ₁₀ Air Particulate Sampling High Volume Method	0	10/01/91
AP.10	Radioactive Ambient Air Monitoring Particulate Sampling Data Reduction	0	10/01/91
AP.11	Mass Flow TSP/PM ₁₀ Calibration, Ambient Air Particulate Sampling High Volume Method	0	10/01/91

**ROCKY FLATS PLANT
EMD OPERATING
PROCEDURES MANUAL**

Manual No.: 5-21000-OPS-AP
Procedure No.: Table of Contents, Rev 1
Page: 2 of 2
Effective Date: 11/11/91
Organization: Environmental Management

<u>Proc. No.</u>	<u>Title</u>	<u>Rev. No.</u>	<u>Effective Date</u>
AP.12	Placement, Design, Installation, and Operation of Meteorological Monitoring Stations		
AP.13	Radioactive Ambient Air Monitoring Program	0	10/01/91
AP.14	Meteorology Data Downloading		
AP.15	Restoration Projects Data Reduction for Radioactive Ambient Air Monitoring	0	10/01/91
AP.16	Restoration Projects Radioactive Ambient Air Particulate Sampling High Volume Method	0	10/01/91
AP.17	Sampling Procedure, Volatile Organic Compounds Method TO-14	0	10/01/91
AP.18	Sampling For Organochlorine Pesticides and Polychlorinated Biphenyls in Ambient Air (SVOD)	0	10/01/91
AP.19	VOC Sampling		
AP.20	SVOC Sampling		
AP.21	Particulate Suspended Metals Sampling		

**ENVIRONMENTAL MANAGEMENT
DOCUMENT CHANGE NOTICE (DCN)**

Procedure Number 5-21000-CPS AP.01 Rev. 0

Page 1 of 1

Title Effluent Tritium Sample Collection				Date <u>11/1/91</u>	DCN Number <u>5-21000-CPS-AP.01 Rev.01</u> This is a			
Expires <u>1/31/92</u>		Procedure Revision Required		CONTROLLED DOCUMENT				
Scope Limitation:				Page <u>598</u>	ROCKY FLATS PLANT EMIRES AREA NUMBER <u>1000</u> DEPARTMENT <u>WASTE COMMAND DEPARTMENT</u>			
Change is this is a RED Stamp (Use DCN CONTINUATION SHEET for additional space)								
Item Number	Page	Step or Paragraph	<p>Revise step 6.2.23 to read:</p> <p>6.2.23 Inspect the seals, vacuum tubing, and other associated equipment for damage or other possible maintenance problems.</p>					
Justification (Reasons for change - Provide numbers to reference corresponding items above.) Inspection of seals required to ensure equipment performance								
Concurrents	Organization	Req.	Date	Concurrents	Organization	Req.	Date	
<u>John S. Doherty</u>	<u>OAPM</u>	<u>X</u>	<u>11/8/91</u>	<u>WIF Only</u>	<u>User</u>		<u>11-9-91</u>	
<u>Approval of Environmental Manager</u> <u>Ralph N. Vetter</u>		Date <u>11-8-91</u>	Is Posting required? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		If Yes, by what date		Date posted	